

Jobling Purser Limited Case Studies

LUCIOL (Diamond Grade) Case Study

Highways Agency Area 14



SITE DETAILS

Site Location: A628 Woodhead Pass
Derbyshire

Date of Installation: December 2001

Site Description: 12 Km section of trunk road characterised by poor forward visibility, sharp bends, lack of carriageway definition and extreme weather.

Accident reducing measures undertaken:

1. Installation of 1000 linear meters of Luciol to existing corrugated and box beam barriers.
2. Improved warning signs.
3. Improved road markings and road studs.
4. High friction surfacing.

Accident statistics prior to application:

32 Injury Accidents per year

Accident statistics after application:
(January 2002 – January 2003)

15 Injury Accidents per year

Summary

As part of this accident reduction scheme, Luciol has contributed to a reduction of 55% in injury accidents in the first year.

Note: This site is used as a case study in the Highways Agency "Good Practice Guide to Route Treatments" published in March 2003.

JOBLING



PURSER
LTD

Jobling Purser Limited
Reg. Office: Paradise Works

Scotswood Road

Newcastle upon Tyne

NE15 6BZ United Kingdom

Tel: +44 (0)191 273 2331

Fax: +44 (0)191 226 0129

E-mail: info@joblingpurser.com

Website: www.joblingpurser.com